

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402557017

Date Received:

12/18/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96155

Name of Operator: WHITING OIL & GAS CORPORATION

Address: 1700 LINCOLN STREET SUITE 4700

City: DENVER State: CO Zip: 80290

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

dnr\_cogccengineering@state.co.us

WhitingEasternCO@Whiting.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696302479

Inspection Date: 09/15/2020

FIR Submit Date: 09/15/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: WHITING OIL & GAS CORPORATION

Company Number: 96155

Address: 1700 LINCOLN STREET SUITE 4700

City: DENVER State: CO Zip: 80290

LOCATION - Location ID: 423627

Location Name: Pawnee Creek 9-57-18 Number: 1M County: WELD

Qtrqr: SENW Sec: 18 Twp: 9N Range: 57W Meridian: 6

Latitude: 40.751642 Longitude: -103.794497

FACILITY - API Number: 05-123- -00 Facility ID: 423673

Facility Name: Pawnee Creek 9-57-18 Number: 1M

Qtrqr: SENW Sec: 18 Twp: 9N Range: 57W Meridian: 6

Latitude: 40.751642 Longitude: -103.794497

CORRECTIVE ACTIONS:

1 CA# 141925

Corrective Action: Repair and maintain lease road to comply with rule 204.

Date: 12/18/2020

Response: CA COMPLETED

Date of Completion: 12/17/2020

Operator Comment: Access road has been repaired to comply with Rule 204. See attached photograph.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**3** CA# 141927

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Date: 12/18/2020

Response: CA COMPLETED

Date of Completion: 12/08/2020

Operator  
Comment:

A mechanical integrity test was completed and a Form 21 has been submitted. Document Number: 402542615

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Bryce Maifeld

Signed: \_\_\_\_\_

Title: Regulatory Specialist

Date: 12/18/2020 10:58:23 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402557053	Photograph
-----------	------------

Total Attach: 1 Files