

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 1 – Tank Battery Sign



Photo 2 – Wellhead



Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 3 – Tank Battery



Photo 4 – Heater Treater

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 5 – ECD and Flare



Photo 6 – Stained Soil at Engine Exhaust

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 7 – Stained Soil at Gas Engine



Photo 8 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Colorado Oil and Gas Conservation Commission
40.59721, -104.31897, 4790.6ft, 207°
12/16/2020 11:10:34

Photo 9 – Unused Supply Pot at Pumping Unit