

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 1 – Tank Battery Sign



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 3 – Wellhead



Photo 4 – Stained Soil at Engine Exhaust

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 5 – Stained Soil at Gas Engine



Photo 6 – Stained Soil at Gas Engine



Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 7 – Tank Battery



Photo 8 – Heater Treater