

Inspection Photos

API: 043-06198

Operator: INCREMENTAL OIL & GAS

Inspection Date: 12/16/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06198 | Date: 12/16/2020

Inspection Photos



Photo 1. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06198 | Date: 12/16/2020

Inspection Photos



Photo 2. The north at the location. Vegetation is well established and the location is stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06198 | Date: 12/16/2020