

# Inspection Photos

API: 041-06051

Operator: ETOCO LP

Inspection Date: 12/16/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 041-06051 | Date: 12/16/2020

## Inspection Photos



**Photo 1.** Facing south at beginning of the access road. The access road has not established vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06051 | Date: 12/16/2020

## Inspection Photos



**Photo 2.** Facing north at the access road. The access road from the location to the gates (red arrow) have not established vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06051 | Date: 12/16/2020



## Inspection Photos



**Photo 3.** Center of the location facing north. The fence around the location has been removed and vegetation appears to be well established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06051 | Date: 12/16/2020

## Inspection Photos



**Photo 4.** Center of the location facing west.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06051 | Date: 12/16/2020



## Inspection Photos



**Photo 5.** Center of the location facing south.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06051 | Date: 12/16/2020

## Inspection Photos



**Photo 6.** Center of the location facing north.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06051 | Date: 12/16/2020