

Interim Reclamation Inspection

December 17, 2020

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 428225

Inspection Document #: 697502324

Weld County, CO

NWSW Section 5 T7N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Drone aerial imagery taken on December 17, 2020. Photo illustrates the Operator has initiated interim reclamation activities to recontour and replace topsoil, but seeding does not appear to have been performed. Operator has not implemented any stormwater BMP's along the downslope of location but did leave the interim areas rough.



Photo 2. Drone aerial imagery taken on December 17, 2020. There were 17 bales of straw mulch at location stored along the southeastern location.

Inspection Photos
Location: Leggett #1-5H
Location ID: 428225



Photo 3. Photo taken from the southern well pad, facing South. See comments under Photo 1.

Inspection Photos
Location: Leggett #1-5H
Location ID: 428225



Photo 4. Photo taken from the southern well pad, facing North. See comments under Photo 1.