

Inspection Photos  
Operator: Simcoe  
API: 067-07379  
Date: 12/17/2020



Photo 1. View of the project area from the southeastern corner facing center.





Photo 2. View of the southern project area from the southeastern corner facing westward. Approximately 250 musk and Canada thistles observed within the interim reclamation areas.





Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area comprised of grass crop field, largely snow covered at this time.