

BP L48 San Juan



V2 Compliance Follow Up Form

18162779119

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20201117-18162779119

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Nov 17, 2020 3:20:12 PM MST

557 Airpark Dr, Durango, CO 81303, USA

Nov 17, 2020 3:19:52 PM MST [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Nov 17, 2020

Well Name

BUSH FEDERAL GAS UNIT 1

API Number

50670711400

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Seeding
Other

Photo of first corrective action completed



Completed work description Corrective
Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

repaired rills, seeded and blanketed slopes

Photo of third corrective action completed



Completed work description of corrective action 3

repaired rills, seeded and blanketed slopes

Photo of fourth corrective action completed



Completed work description

repaired rills, seeded and blanketed slopes

Completed work description of corrective action 4

repaired rills, seeded and blanketed slopes

Additional photos



Additional photos



Additional photos



Additional photos



Completed work description
Summary of all work completed

repaired rills, seeded and blanketed slopes
installed erosion control blanket on slopes



Rip rap the erosion channel coming onto the pad.