

# Inspection Photos

API: 071-09252

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 12/22/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 12/22/2020

## Inspection Photos



**Photo 1.** Facing west toward the access road which has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 12/22/2020

## Inspection Photos



**Photo 2.** Facing northwest along the access road toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 12/22/2020

## Inspection Photos



**Photo 3.** Facing northwest toward the location. The location has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 12/22/2020

## Inspection Photos



**Photo 4.** Facing east toward the fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 12/22/2020

## Inspection Photos



**Photo 5.** Center of the location facing northwest.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 12/22/2020