

# Inspection Photos

API: 071-09465

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 12/22/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09465 | Date: 12/22/2020

## Inspection Photos



**Photo 1.** Facing southwest toward the access road which has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09465 | Date: 12/22/2020

## Inspection Photos



**Photo 2.** Facing south toward the location which has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09465 | Date: 12/22/2020

## Inspection Photos



**Photo 3.** Facing toward the west fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09465 | Date: 12/22/2020

## Inspection Photos



**Photo 4.** Facing south toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09465 | Date: 12/22/2020

## Inspection Photos



**Photo 5.** Facing north at the east side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09465 | Date: 12/22/2020

## Inspection Photos



**Photo 6.** View of the location from a distance across the canyon.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09465 | Date: 12/22/2020