

# Inspection Photos

11/24/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 312659

Mesa County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312659



**Photo 1:** Photo taken from the north end of the Location, facing southeast. Photos 1-3 provide an overview of the Location from southeast, south to southwest. Access road through Location has not been reclaimed and remains needed for access to the NICHOLS FEDERAL #13-3H; Reclamation of access road required during reclamation of the 13-3H.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312659



**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312659



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312659



**Photo 4:** Photo shows example of what appears to be a Scotch Thistle rosette observed on Location.