

Inspection Photos  
Operator: Simcoe  
API: 067-07720  
Date: 12/23/2020



Photo 1. View of the project area from the well pad entrance facing center. Musk thistles observed at the well pad entrance.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Project area is largely snow covered. Vegetation is in a grazed condition similar to surrounding field.





Photo 3. View of reference area comprised of open field, largely snow covered. Vegetation appears to be in a grazed vegetative condition.