

Inspection Photos

Loc#334944

Operator: Caerus

Insp #692402779

Insp Date: 12/16/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to West. Insert; BMP NW end of site

December 16, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzel Loc#334944