

Inspection Photos

Location Name: Lauridson VV 18-10

Location ID: 329482

Dec 30, 2020 at 1:02:00 PM
40.049764,-104.931212
Dacono CO 80621
United States
COGCC



Pic 1 fence not installed correctly



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources