



40.09884, -108.85687, 5141.8ft, 26°
12/28/2020 10:32:42 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.


McLaughlin SR 17

API: 05-103-40158

Inspection: 700404792



40.09885, -108.85683, 5137.1ft, 346°
12/28/2020 10:33:00 AM



40.09889, -108.85692, 5177.2ft, 6°
12/28/2020 10:51:33 AM



40.09882, -108.8568, 5133.3ft, 21°
12/28/2020 10:33:14 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Power panel.

McLaughlin SR 17

API: 05-103-40158

Inspection: 700404792



40.09912, -108.85588, 5156.3ft, 22°
12/28/2020 10:55:53 AM