



40.09784, -108.85574, 5158.8ft, 61°
12/28/2020 11:03:19 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

McLaughlin SR 6

API: 05-103-05500

Inspection: 700404795



40.09782, -108.85574, 5155.7ft, 48°
12/28/2020 11:03:44 AM



40.0978, -108.85564, 5155.6ft, 331°
12/28/2020 11:04:00 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Oil spill.

McLaughlin SR 6

API: 05-103-05500

Inspection: 700404795



40.09782, -108.85566, 5154.6ft, 4°
12/28/2020 11:04:23 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Well.

McLaughlin SR 6

API: 05-103-05500

Inspection: 700404795





40.09771, -108.85564, 5159.6ft, 10°
12/21/2020 11:05:07 AM