



Energy Inc.

Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Kenny Canterbury
Submission Date: 12/31/2020
Server Receive Date: 11/12/2020
Reference Number: [Click here to enter text.](#)
Location: Southern Ute 29-1 2

Information

Name: Kenny Canterbury
Date of work completion: 12/23/2020
Well Name: Southern Ute 29-1 2
API Number: 05-067-06783
Select State: Colorado
Work type: SUIT Inspection
Inspection Number (Inspection # from SOW): 693902451

Special Notes: Fixed erosion, installed rip rap rundowns, created diversion ditch, cleaned up stains and picked up trash.

Action Complete

Other *must specify in notes*

Photo of above state work completion



Choose an item.



Choose an item.



Choose an item.



Choose an item.



Choose an item.

