

Inspection Photos

Loc#335434

Operator: Terra

Insp#: 692402809

Insp Date: 12/22/20





Photo#1:
Overview of Location from entry.

December 22, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal Loc#335434



Photo#2:
North side Cut Slope.



Photo#3:
North side Cut Slope.

December 22, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal Loc#335434



Photo#4:
Debris on Southwest side of Pad.
December 22, 2020

Photo#5:
Debris on Southwest side of Pad.



Photo#6:
Debris weeds.

December 22, 2020



Photo#7:
Debris weeds. Insert, area where it appears weeds
were cleaned out.

