

Inspection Photos

Loc#335432

Operator: Terra

Inspection Number: 692402811

Inspection Date: 12/22/20





Photo#1:
Overview of Location from Entry.

December 22, 2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal Loc#335432



Photo#2:
BMP.



Photo#3:
BMP.

December 22, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal Loc#335432



Photo#4:
Panel Repaired.



Photo#5:
Tamarisk.

December 22, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal Loc#335432