

Inspection Photos

Loc#335225

Operator: Terra

Insp#: 692402814

Insp Date: 12/22/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry.

December 22, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Savage Loc#335225



Photo#2:
Cut slope on upper level.



Photo#3:
Area behind tanks on lower level.

December 22, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Savage Loc#335225