

Inspection Photos

Loc#335195

Operator: Terra

Insp#: 692402822

Insp Date: 12/23/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location over Interim area.

October 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Jonsson Loc#335195



Photo#2:
Kochia growth on edge of access road.



Photo#3:
Kochia growth on areas of pad receiving limited to
no vehicle traffic.

October 29, 2020



Photo#4:
Kochia growth on Interim area.



Photo#5:
Kochia growth on areas of pad receiving limited to
no vehicle traffic.

October 29, 2020