



**Inspection Photos**  
**Location Name: Pronghorn P-16 PAD**  
**Location ID: 428090**



**Photo 1 – 31-34-16HNB Pumping Unit**




**Photo 2 – 41-44-16HZ Wellhead**



**Inspection Photos**  
**Location Name: Pronghorn P-16 PAD**  
**Location ID: 428090**



**Photo 3 – 31-34-16HMB Tank Battery**



**Photo 4 – Tank Battery Sign**



**Inspection Photos**  
**Location Name: Pronghorn P-16 PAD**  
**Location ID: 428090**



**Photo 5 – Separator, ECDs**



**Photo 6 – Separator, ECDs**

**Inspection Photos**  
**Location Name: Pronghorn P-16 PAD**  
**Location ID: 428090**



**Photo 7 – 41-44-16HZ Tank Battery**



**Photo 8 – 2" Riser Unmarker**





Inspection Photos  
Location Name: Pronghorn P-16 PAD  
Location ID: 428090



Photo 9 – Unmarked Risers



Photo 10 – 2" Riser Unmarker

