

Inspection Photos
Location Name: Pronghorn T-P-4HNB
Location ID: 431481



Photo 1 – Sign at Entrance

Photo 2 – Tank Battery

Inspection Photos
Location Name: Pronghorn T-P-4HNB
Location ID: 431481



Photo 3 – Separators




Photo 4 – Pumping Unit, TA Wellhead

Inspection Photos
Location Name: Pronghorn T-P-4HNB
Location ID: 431481



Photo 5 – Tank Battery Sign

Photo 6 – Unmarked Riser

Inspection Photos
Location Name: Pronghorn T-P-4HNB
Location ID: 431481



Photo 7 – Unmarked Riser



Photo 8 – Riser have been marked

Inspection Photos
Location Name: Pronghorn T-P-4HNB
Location ID: 431481



Photo 9 – Unmarked Riser



Photo 10 – Unmarked Riser

Inspection Photos
Location Name: Pronghorn T-P-4HNB
Location ID: 431481



Photo 11 – Unmarked Riser



Photo 12 – Unmarked Riser