

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402566601

Date Received:  
01/05/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

.Grizzly

aaxelson@grizzlyenergyllc.com

.Grizzly

sghan@grizzlyenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700702048

Inspection Date: 12/21/2020

FIR Submit Date: 12/21/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC

Company Number: 10531

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 335227

Location Name: BROOME-66S91W Number: 30SESE County: \_\_\_\_\_

Qtrqtr: SESE Sec: 30 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.493591 Longitude: -107.590921

FACILITY - API Number: 05-045- -00 Facility ID: 335227

Facility Name: BROOME-66S91W Number: 30SESE

Qtrqtr: SESE Sec: 30 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.493591 Longitude: -107.590921

CORRECTIVE ACTIONS:

1 CA# 145244

Corrective Action: remove unused equipment/debris

Date: 01/21/2021

Response: CA COMPLETED

Date of Completion: 12/28/2020

Operator  
Comment:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

COGCC Decision: \_\_\_\_\_

\_\_\_\_\_

The alleged slope stabilization issue behind tank battery will be addressed when onsite and winter weather conditions allow.

\_\_\_\_\_

Date: 1/5/2021 2:15:53 PM

Page 2 of 2