

Inspection Photos
Location Name: Gold 9 NU
Location ID: 302527



Colorado Oil & Gas Conservation Commission
40.33181, -104.8968, 1449.3m, 57°
01/06/2021 13:26:14

Production facility



Colorado Oil & Gas Conservation Commission
40.33085, -104.89673, 1443.0m, 356°
01/06/2021 14:25:48

Wellhead

Inspection Photos
Location Name: Gold 9 NU
Location ID: 302527



Master valve leak



Stained soil

Inspection Photos
Location Name: Gold 9 NU
Location ID: 302527



Lubricator leak



Lubricator leak