

# Inspection Photos

1/04/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 323949


Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 323949



**Photo 1:** Photo taken from the Location facing North. Photo shows the single producing well on Location. All other permitted wells have been abandoned.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 323949



**Photo 2:** Photo taken from the north end of the Location, facing north. Photos 2-5 provide an overview of the Location from North, Northeast, Southeast to South.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 323949



**Photo 3:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 323949



**Photo 4:** See comments under photo 1.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 323949



**Photo 5:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 323949



**Photo 6:** Photo taken from the east end of the Location, facing east. Photo shows pipe debris.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 323949



**Photo 7:** Photo taken from the east end of the Location, facing west. Photo shows pipe debris.

