

Inspection Photos  
Operator: Simcoe  
API: 067-08817  
Date: 1/6/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with shrubs and grasses such as fourwing saltbush, rubber rabbitbrush, western wheatgrass, and crested wheatgrass.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of trash and debris dumped on the well pad. Additional trash scattered around the well pad.



Photo 5. View of reference area comprised of pinyon and juniper woodland with sagebrush, squirreltail, and narrow leaf penstemon.