

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402569730
Receive Date:
01/08/2021
Report taken by:
KRIS NEIDEL

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation. Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>WEXPRO COMPANY</u>	Operator No: <u>95960</u>	Phone Numbers
Address: <u>P O BOX 45003</u>		
City: <u>SALT LAKE CITY</u>	State: <u>UT</u>	Phone: <u>(307) 352-7561</u>
	Zip: <u>84145-0601</u>	Mobile: <u>(307) 371-3610</u>
Contact Person: <u>April Stegall</u>	Email: <u>april.stegall@dominionenergy.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION
Remediation Project #: 8641 Initial Form 27 Document #: 2141609

PURPOSE INFORMATION

<input type="checkbox"/> 901.e. Sensitive Area Determination	<input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
<input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure	<input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
<input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation	<input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project
<input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste	<input type="checkbox"/> Rule 906.c.: Director request
<input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure	<input checked="" type="checkbox"/> Other <u>Variance request, please see comments</u>

SITE INFORMATION N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>PIT</u>	Facility ID: <u>100611</u>	API #: _____	County Name: <u>MOFFAT</u>
Facility Name: <u>JACKS DRAW UNIT 13</u>	Latitude: <u>40.983888</u>	Longitude: <u>-108.284687</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NWSW</u>	Sec: <u>22</u>	Twp: <u>12N</u>	Range: <u>97W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use RANGELAND

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

NATURAL DRAINAGE APPROXIMATELY 80' FROM WELL PAD.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input checked="" type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input checked="" type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	None	Visual inspection
Yes	SOILS	See analysis	SOIL ANALYSIS TO BE PERFORMED
Yes	SURFACE WATER	NONE	VISUAL - LOCATION BELOW DRAINAGE

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

VISUAL INSPECTION. SOIL ANALYSIS WILL BE OBTAINED PER TABLE 910-1. SAMPLE LOCATIONS WILL BE GUIDED BY RULE 910.B.(3)B. FENCING WILL REMAIN IN PLACE TO PREVENT INTRUSION BY STOCK OR WILDLIFE. SURFACE OWNER (BLM) WILL BE NOTIFIED OF SAMPLE RESULTS.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Please see the attachment for soil analysis from samples obtained in 2020.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

No groundwater has been encountered during sampling. If groundwater is encountered during remediation, COGCC will be notified immediately.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 3
Number of soil samples exceeding 910-1 3
Was the areal and vertical extent of soil contamination delineated? No
Approximate areal extent (square feet) 460

NA / ND

-- Highest concentration of TPH (mg/kg) 1300
-- Highest concentration of SAR 104
BTEX > 910-1 No
Vertical Extent > 910-1 (in feet) 8

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? No
Depth to groundwater (below ground surface, in feet) \
Number of groundwater monitoring wells installed
Number of groundwater samples exceeding 910-1

Highest concentration of Benzene (µg/l)
Highest concentration of Toluene (µg/l)
Highest concentration of Ethylbenzene (µg/l)
Highest concentration of Xylene (µg/l)
Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected
 Number of surface water samples exceeding 910-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) Volume of liquid waste (barrels)

Is further site investigation required?

Delineation has not been performed. Wexpro Company proposes that delineation of the pit be completed as contaminated soils are removed.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Wexpro Company proposes to remove the contaminated soil from this pit by excavation (most likely backhoe) and haul to an approved disposal facility, as the last round of sampling does not meet Table 910-1 standards, please see attachment.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Wexpro Company requests approval to delineate the contamination of this pit while excavating soils to be hauled to an approved facility. If possible, a PID meter will be used to periodically gauge whether or not the contamination has been removed during excavation. If no PID is available, Wexpro Company will re-sample the excavated area after it is believed that all contamination has been removed, for confirmation. Wexpro Company will test the excavated area for all Table 910-1 constituents, with the exception of: EC, SAR and arsenic, as contamination is below 3 feet and will not affect the root zone, so remediation of EC and SAR impacts are not needed and it has been previously proven that the area has naturally high levels of arsenic. Soil analysis of the excavated area will be submitted with request for closure before the pit is backfilled. The pit will be fenced until approval to backfill has been received, so as to prevent intrusion from wildlife and livestock. The BLM (surface owner) will be notified of this plan, and excavation will begin, weather permitting, once all agency approvals have been received.

Soil Remediation Summary

In Situ

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

Ex Situ

- Yes _____ Excavate and offsite disposal
- _____ If Yes: Estimated Volume (Cubic Yards) _____ 0
- _____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
- _____ Excavate and onsite remediation
- _____ Land Treatment
- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Other _____

Groundwater Remediation Summary

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

NA, not necessary. Groundwater has not been encountered during sampling and previous remediation activities. If groundwater is encountered during excavation, COGCC will be notified immediately.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: Quarterly Semi-Annually Annually Other As work is completed.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No _____

Do all soils meet Table 910-1 standards? No _____

Does the previous reply indicate consideration of background concentrations? _____

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? Yes _____

Does Groundwater meet Table 910-1 standards? Yes _____

Is additional groundwater monitoring to be conducted? No _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The pit will be backfilled to grade upon approval of soil analysis that meets Table 910-1 requirements. Final reclamation of the previously P&A'd well pad will be completed after approval to backfill the pit.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim? Final?

Did the Surface Owner approve the seed mix? Yes _____

If NO, does the seed mix comply with local soil conservation district recommendations? Yes _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). _____

Date of commencement of Site Investigation. 08/25/2020

Date of completion of Site Investigation. 08/25/2020

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

Wexpro Company requests permission to complete remediation of this pit under the Table 910-1 requirements, as remediation is in progress and will be completed by January 2022.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: April Stegall _____

Title: Reclamation Agent _____

Submit Date: 01/08/2021 _____

Email: april.stegall@dominionenergy.com _____

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KRIS NEIDEL _____

Date: 01/08/2021 _____

Remediation Project Number: 8641 _____

COA Type

Description

	If Remediation at site is not completed by January 15, 2022, then the Operator will comply with the current version of Table 915-1.
--	---

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

402569730	FORM 27-SUPPLEMENTAL-SUBMITTED
-----------	--------------------------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)