

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNOX /03-08 PAD

Location ID: 414268



Photo #2582 from entrance to location.



Photo #2583 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNOX /03-08 PAD

Location ID: 414268



Photo #2584 Hole in tank containment liner.