

Inspection Photos

1/11/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 323893

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 1: 2019 COGIS aerial image. Photo shows two parallel access roads leading to the CC 0604-1 Pad, and the Cascade Creek 697-04D. This does not comport with Rule 1002.e “surface disturbance minimization” requirements regarding access roads. Roads identified in yellow will require reclamation.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 2: 2011 Google Earth aerial image. Red line shows the eastern edge of the access road. Access road was constructed and further expanded east sometime between 2011 and 2014.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 3: 2016 Google Earth aerial image. Red line shows the eastern edge of the access road prior to the additional eastern expansion of the road. The original access road has not been recontoured/regraded/reclaimed, and will now also be included within the corrective action requirements for reclamation.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 4: Two access roads travel parallel north and south of one another. Photo shows the access road that travels from the southwestern end of the CC 0604-1 Pad Location, facing south.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 5: Photo taken from the south of the CC 0604-1 Pad Location, facing north. Photo shows the two parallel access roads that travel from the CC 0604-1 Pad Location, and the Cascade Creek 697-04D Location (See photo 1).

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 6: Photo taken from the west end of the Location. Photo shows container stored on location. The corrective action requiring removal of container is no longer applicable.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 7: Photo taken from the west end of the Location. Photo shows trash dumpster stored on location. The corrective action requiring removal of container is no longer applicable.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 8: Photo taken from the north end of the CC 0604-1 Pad Location, facing north. Photo shows the two parallel access roads that travel from the CC 0604-1 Pad Location, and the Cascade Creek 697-04D Location (See photo 1).

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 9: Photo taken from the north end of the CC 0604-1 Pad Location, facing south. There are currently 2 access roads, and 4 access points (on the northwest, northeast, southwest and southeast) to the CC 0604-1 Pad . Photo shows eastern access road

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 10: Continued from photo 9. Between 2011 and 2014, the access road in this area was further expanded to the east (red arrow). This photo shows that the original access road (yellow arrow) was not reclaimed; These areas will also require reclamation including, but not limited to, compaction alleviation, recontouring/regrading and revegetation.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 11: Photo taken from the southwest corner of the Cascade Creek 697-04D location. Photo shows additional access road leading to the CC 0604-1 Pad. This is additional disturbance that does not comport with Rule 1002.e

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 12: Photo taken from the south of the CC 0604-1 Pad Location, facing north. Photo shows the two access roads that run parallel to one another to the CC 0604-1 Pad. Photo also shows the section of the original access road (continued from photo 10, yellow arrows) that was not reclaimed when the access road was expanded further east between 2011 and 2014. These areas will also require reclamation including, but not limited to, compaction alleviation, recontouring/regrading and revegetation.