

# Inspection Photos

1/08/2021

Operator: GORDON ENGINEERING INC -  
34720

Location ID: 312560  
Mesa County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: GORDON ENGINEERING INC - 34720  
Location ID: 312560



**Photo 1:** Photo taken from the access road, facing east towards the Location. Photo shows Final Reclamation of the access road, including recontouring/regrading, has not been conducted/completed per corrective actions.

Inspection Photos  
Operator Name: GORDON ENGINEERING INC - 34720  
Location ID: 312560



**Photo 2:** Photo taken from the access road, facing east towards the Location. Photo shows Final Reclamation of the access road, including recontouring/regrading, has not been conducted/completed per corrective actions.





## Inspection Photos

Operator Name: GORDON ENGINEERING INC - 34720

Location ID: 312560



**Photo 3:** Photo taken from the west end of the Location, facing northeast. Photos 3-5 provide an overview of the Location from northeast, east to southeast. Photos shows Final Reclamation of the Location, including recontouring/regrading, replacement of soils, etc... has not been conducted/completed per corrective actions.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: GORDON ENGINEERING INC - 34720

Location ID: 312560



**Photo 4:** See comments under photo 3.



Inspection Photos  
Operator Name: GORDON ENGINEERING INC - 34720  
Location ID: 312560



**Photo 5:** See comments under photo 3.





Inspection Photos  
Operator Name: GORDON ENGINEERING INC - 34720  
Location ID: 312560



**Photo 6:** Photo taken from areas north of the Location, where cement waste material was spilled onto. Photo shows that due to snow cover, Reclamation Specialist was unable to accurately assess whether or not corrective action was addressed.

