

Inspection Photos
Location Name: Anschutz-Obrien 5-61-33-57H
Location ID: 430166



Photo 1 – Wellhead



Photo 2 – Tank Battery Signs

Inspection Photos
Location Name: Anschutz-Obrien 5-61-33-57H
Location ID: 430166



Photo 3 – Tank Battery, NW Tank missing Labels



Photo 4 – Separator and Gas Meters

Inspection Photos
Location Name: Anschutz-Obrien 5-61-33-57H
Location ID: 430166



Photo 5 – ECD



Photo 6 – Condensate Tank now has Capacity Label

Inspection Photos
Location Name: Anschutz-Obrien 5-61-33-57H
Location ID: 430166



Photo 7 – Risers have been marked



Photo 8 – Risers have been marked



Inspection Photos
Location Name: Anschutz-Obrien 5-61-33-57H
Location ID: 430166



Photo 9 – Risers have been marked