

**Inspection Photos**  
**Location Name: Pronghorn V-32 PAD**  
**Location ID: 438730**



**Photo 1 – Signs at Entrance**

**Photo 2 – Wellhead**

**Inspection Photos**  
**Location Name: Pronghorn V-32 PAD**  
**Location ID: 438730**



Colorado Oil and Gas Conservation Commission  
40.36081, -104.22597, 4498.4ft, 259°  
01/06/2021 12:53:35

**Photo 3 – Wellheads**



Colorado Oil and Gas Conservation Commission  
40.36047, -104.22603, 4512.4ft, 226°  
01/06/2021 12:52:55

**Photo 4 – Separators**



**Inspection Photos**  
**Location Name: Anschutz-Obrien 5-61-33-57H**  
**Location ID: 430166**



**Photo 5 – Maintenance Tank**



**Photo 6 – Gas Lift Meter Shed**

**Inspection Photos**  
**Location Name: Pronghorn V-32 PAD**  
**Location ID: 438730**



**Photo 7 – ECDs**



**Photo 8 – Tank Battery**

**Inspection Photos**  
**Location Name: Pronghorn V-32 PAD**  
**Location ID: 438730**



**Photo 9 – Tank Battery Signs**



**Photo 10 – Compressor**



**Inspection Photos**  
**Location Name: Pronghorn V-32 PAD**  
**Location ID: 438730**



**Photo 11 – Drain Pit now has Signs**



**Photo 12 – Drain Pit now has Signs**



**Inspection Photos**  
**Location Name: Pronghorn V-32 PAD**  
**Location ID: 438730**



**Photo 13 – Riser at Compressor marked**



**Photo 14 – Riser at Compressor marked**

**Inspection Photos**  
**Location Name: Pronghorn V-32 PAD**  
**Location ID: 438730**



**Photo 13 – Day Tank Containment Netting is in disrepair**



**Photo 14 – Compressor**