

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402474740

Date Received:

08/25/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|---------------------------|----------------------------------|------------------------------------|
| <u>Mattorano, Michael</u> | <u>575-445-6704/505-652-0416</u> | <u>mmattorano@wapitienergy.com</u> |
| <u>Berry, Matthew</u> | <u>575-445-6785/505-652-8275</u> | <u>mberry@wapitienergy.com</u> |
| <u>Madison, Randy</u> | <u>575-445-6706/575-420-1120</u> | <u>rmadison@wapitienergy.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 695103168

Inspection Date: 08/18/2020

FIR Submit Date: 08/18/2020

FIR Status: _____

Inspected Operator Information:

Company Name: WAPITI OPERATING LLC

Company Number: 10351

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

LOCATION - Location ID: 307766

Location Name: VPR C-635S66W Number: 16SENW County: LAS ANIMAS

Qtrqtr: SENW Sec: 16 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.000710 Longitude: -104.788780

FACILITY - API Number: 05-071- -00 Facility ID: 256741

Facility Name: VPR C Number: 29

Qtrqtr: SENW Sec: 16 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.000710 Longitude: -104.788780

CORRECTIVE ACTIONS:

1 ☒ CA# 141323

Corrective Action: PROVIDE AREA FIELD INSPECTOR (@ tombeardslee@state.co.us) A COPY OF THE GAS METER CALIBRATION RECORD OR KEEP A COPY OF LAST CALIBRATION RECORD ON LOCATION.

Date: 09/18/2020

Response: CA COMPLETED

Date of Completion: 08/25/2020

See attached Meter/Calibration Inspection report

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 141324

Corrective Action: REMOVE IMPACTED SOIL, Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.

Date: 11/18/2020

Response: CA COMPLETED

Date of Completion: 08/25/2020

Operator
Comment:

Impacted soil was removed and disposed of properly

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 141325

Corrective Action: PLUMB BRADENHEAD TO SURFACE, COMPLY WITH RULE 608e. CA DATE 11-18-20.

Date: 11/18/2020

Response: CA COMPLETED

Date of Completion: 08/25/2020

Operator
Comment:

Bradenhead has been plumbed to the surface see attached photo

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy L. Madison

Signed: _____

Title: HSE Specialist

Date: 8/25/2020 2:12:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------------|
| 402474740 | FIR RESOLUTION SUBMITTED |
| 402474742 | Meter/Calibration Report |
| 402474743 | Well Head Clean-up |
| 402474744 | Bradenhead Plumbed |

Total Attach: 4 Files

Date Run: 1/12/2021 Doc [#402474740]

Page 2 of 2