

# Final Reclamation Inspection

January 14, 2021

Operator: CARRIZO OIL & GAS INC - #10338

Location ID: 438115

Inspection Document #: 697502445

Weld County, CO

Lot 3 Section 2 T8N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Ross #1-2-8-61  
Location ID: 438115



**Photo 1.** Photo taken from the location, facing Southwest. Photo illustrates location was not constructed at the proposed well location based off field observations.

