

Inspection Photos

1/19/2021

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 314732

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 314732



Photo 1: Photo taken from the west end of the Location, facing north. Photos 1-3 provide an overview of the Location from north, east to south. Photo also shows cut/soils on the north end of the Location that have not been contoured/replaced.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 314732



Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 314732



Photo 3: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314732



Photo 4: Photo taken from the south end of the Location. Photo shows utility pole equipment remaining on the Location.



Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314732



Photo 5: Photo of well marker on Location.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314732



Photo 6: Photo taken from the east end of the Location, facing west. Photo shows pipe riser equipment observed remaining on Location.



Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314732



Photo 7: Photo taken from the north end of the Location, facing east. Photo shows cut/soils on the north end of the Location that have not been contoured/replaced.

