

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/19/2021

Submitted Date:

01/22/2021

Document Number:

701002177

FIELD INSPECTION FORM
 Loc ID 438106 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 38 PALMER CREST CT

City: SPRING State: TX Zip: 77381

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437864	WELL	PR	08/05/2014	GW	125-12084	Hays 32-03 2S44W	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at unit		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease signs for associated wells at meter sheds		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Metal panels and wire fence around VGS and meter sheds		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 8		
Comment:	8-Vertical gas separators 50% buried by meter sheds		
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:	Shared meter run for (Hays 3-1, 3-6, 3-8, 3-10, 3-15, 31-03, 32-03, Hays State 2-5)		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Kubota gas engine		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Gas scrubber and telemetry equipment at meter sheds		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	437864	Type:	WELL	API Number:	125-12084	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Hays 3-1, 3-6, 3-8, 3-10, 3-15, 31-03, 32-03, Hays State 2-5) 880' SE @ 39.91219/-102.28465								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT