

Inspection Photos
Location Name: LETTERLY USX AB /23-09P
Location #: 418662



Colorado Oil & Gas Conservation Commission
Weld
+40.557470, -104.508907
275° W
22-Jan-2021 13:43

Photo #1

Letterly USX AB 23-09P (05-123-31972) Wellsite
Shut-In | SI



Colorado Oil & Gas Conservation Commission
Weld
+40.558981, -104.507251
194° S
22-Jan-2021 14:16

Photo #2

Letterly USX AB 23-09P Battery site
Inactive | Shut-down

Inspection Photos
Location Name: LETTERLY USX AB /23-09P
Location #: 418662



Colorado Oil & Gas Conservation Commission
Weld
+40.558796,-104.507301
256° W
22-Jan-2021 14:21

Photo #3
Letterly USX AB 23-09P Battery site
Inactive | Shut-down
Battery sign