

Final Reclamation Inspection

January 29, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 322731

Inspection Document #: 697502508

Weld County, CO

NWSE Section 36 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE #3-36
Location ID: 322731



Photo 1. Photo taken from the well location, facing East. Photo illustrates the well location does not meet Rule 1004 vegetative standards and is not reflective of reference area levels.



Inspection Photos
Location Name: STATE #3-36
Location ID: 322731



Photo 2. Photo taken from the well location, facing South. See comments under Photo 1. Reference area is above the red-dashed line and well location is below the red-dashed line.



Inspection Photos
Location Name: STATE #3-36
Location ID: 322731



Photo 3. Photo taken from the well location, facing West. See comments under Photo 1. Reference area is above the red-dashed line and well location is below the red-dashed line.



Inspection Photos
Location Name: STATE #3-36
Location ID: 322731



Photo 4. Photo taken from the well location, facing Northwest. See comments under Photo 1.

