

Inspection Photos

Loc#334830

Operator: Caerus

Insp#: 692402981

Insp Date: 1/27/21





Photo#1:
Overview of Location to West.

January 27, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Graham Loc#334830



Photo#2:
Interim area.



Photo#3:
Pad perimeter.

January 27, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Graham Loc#334830