

Inspection Photos
Operator: Logos
API: 067-07950
Date: 1/29/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Location largely snow covered. Taller perennial vegetation such as western wheatgrass through snow.



Photo 3. View of Scotch thistles within the eastern reclamation areas. Approximately 50 individuals observed.



Photo 4. View of the reference area comprised of open pasture, largely snow covered at this time.