

Inspection Photos
Location Name: Grassy Creek Coal Co 2
Location ID: 316747



Photo 1. Overview of location taken facing east.



Inspection Photos
Location Name: Grassy Creek Coal Co 2
Location ID: 316747



Photo 2. No bradenhead access apparent.



Photo 3. Tubing stored on location.

