

Inspection Photos

ID: 150131

Operator: STRACHAN EXPLORATION INC

Inspection Date: 2/2/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 150131 | Date: 2/2/2021

Inspection Photos



Photo 1. Facing east at the beginning of the access road. The road associated with the abandoned tank battery will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 2/2/2021

Inspection Photos



Photo 2. Facing north along the access road associated with the tank battery. The road will need to be recontoured, decompacted, and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 2/2/2021

Inspection Photos



Photo 3. Facing northeast at the tank battery site located 1600' northwest of the Salt Lake Unit. All equipment has been removed. The access road and location will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 2/2/2021

Inspection Photos



Photo 4. The soil are compacted and bare of vegetation. The location will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 2/2/2021

Inspection Photos



Photo 5. A post remains at north side of the location. The location will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 2/2/2021

Inspection Photos



Photo 6. Facing northwest at the location. The soils are bare of vegetation and must be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 2/2/2021

Inspection Photos



Photo 7. Facing west toward the surrounding undisturbed pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 2/2/2021

Inspection Photos



Photo 8. Facing toward the road which leads the Salt Lake Unit. The road was too wet to travel so the inspection could not be completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 2/2/2021