

# *Inspection Photos*

*ALs Loc#335524*

*Operator: Laramie*

*Insp#: 692402974*

*Insp Date: 1/29/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to East.

North end berm & drains >>>



January 29, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Laramie ALs RMV Loc#335524



Photo#2:  
Overview of Location to Northwest.

January 29, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Laramie ALs RMV Loc#335524





Photo#3:

View over Northeast corner of site. Red arrow = berm drain. Blue arrow = new fence line.

January 29, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Laramie ALs RMV Loc#335524





Photo#4:  
Weedy portion of site, view North.

January 29, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#5:  
View West over Location.

Laramie ALs RMV Loc#335524





Photo#6:  
Drains along North berm.

January 29, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#7:  
Drains along North berm.

Laramie ALs RMV Loc#335524





Photo#8:  
Water drains to north berm and drains.



Photo#9:  
Drains discharge into Gullies to North.

January 29, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Laramie ALs RMV Loc#335524