



**CHANGE OR ADD OBJECTIVE FORMATION AND/OR SPACING UNIT**

<u>Objective Formation</u>	<u>Formation Code</u>	<u>Spacing Order Number</u>	<u>Unit Acreage</u>	<u>Unit Configuration</u>

**OTHER CHANGES**

☐ **REMOVE FROM SURFACE BOND** Signed surface use agreement is a required attachment

☐ **CHANGE OF WELL, FACILITY OR OIL & GAS LOCATION NAME OR NUMBER**

From: Name CHAMPLIN 75 AMOCO 'K' Number 2 Effective Date: \_\_\_\_\_

To: Name \_\_\_\_\_ Number \_\_\_\_\_

☐ **ABANDON PERMIT: Permit can only be abandoned if the permitted operation has NOT been conducted. Field inspection will be conducted to verify site status.**

☐ WELL: Abandon Application for Permit-to-Drill (Form 2) – Well API Number \_\_\_\_\_ has not been drilled.

☐ PIT: Abandon Earthen Pit Permit (Form 15) – COGCC Pit Facility ID Number \_\_\_\_\_ has not been constructed (Permitted and constructed pit requires closure per Rule 905)

☐ CENTRALIZED E&P WASTE MANAGEMENT FACILITY: Abandon Centralized E&P Waste Management Facility Permit (Form 28) – Facility ID Number \_\_\_\_\_ has not been constructed (Constructed facility requires closure per Rule 908)

OIL & GAS LOCATION ID Number: \_\_\_\_\_

☐ Abandon Oil & Gas Location Assessment (Form 2A) – Location has not been constructed and site will not be used in the future.

☐ Keep Oil & Gas Location Assessment (Form 2A) active until expiration date. This site will be used in the future.

**Surface disturbance from Oil and Gas Operations must be reclaimed per Rule 1003 and Rule 1004.**

☐ **REQUEST FOR CONFIDENTIAL STATUS**

☐ **DIGITAL WELL LOG UPLOAD**

☐ **DOCUMENTS SUBMITTED** Purpose of Submission: \_\_\_\_\_

**RECLAMATION****INTERIM RECLAMATION**

☐ Interim Reclamation will commence approximately \_\_\_\_\_

Per Rule 1003.e.(3) operator shall submit Sundry Notice reporting interim reclamation is complete and site is ready for inspection when vegetation reaches 80% coverage.

☐ Interim reclamation complete, site ready for inspection.

Per Rule 1003.e(3) describe interim reclamation procedure in Comments below or provide as an attachment and attach required location photographs.

**Field inspection will be conducted to document Rule 1003.e. compliance**

**FINAL RECLAMATION**

☐ Final Reclamation will commence approximately \_\_\_\_\_

Per Rule 1004.c.(4) operator shall submit Sundry Notice reporting final reclamation is complete and site is ready for inspection when vegetation reaches 80% coverage.

☐ Final reclamation complete, site ready for inspection. Per Rule 1004.c(4) describe final reclamation procedure in Comments below or provide as an attachment.

**Field inspection will be conducted to document Rule 1004.c. compliance**

Comments:

#### ENGINEERING AND ENVIRONMENTAL WORK

##### ☐ NOTICE OF CONTINUED TEMPORARILY ABANDONED STATUS

Indicate why the well is temporarily abandoned and describe future plans for utilization in the COMMENTS box below or provide as an attachment, as required by Rule 319.b.(3).

Date well temporarily abandoned \_\_\_\_\_ Has Production Equipment been removed from site? \_\_\_\_\_

Mechanical Integrity Test (MIT) required if shut in longer than 2 years. Date of last MIT \_\_\_\_\_

☐ SPUD DATE: \_\_\_\_\_

#### TECHNICAL ENGINEERING AND ENVIRONMENTAL WORK

Details of work must be described in full in the COMMENTS below or provided as an attachment.

☐ NOTICE OF INTENT Approximate Start Date \_\_\_\_\_

☒ REPORT OF WORK DONE Date Work Completed 10/21/2020

- |  |   |  |
|--|---|--|
| <input type="checkbox"/> Intent to Recomplete (Form 2 also required) | <input type="checkbox"/> Request to Vent or Flare   | <input type="checkbox"/> E&P Waste Mangement Plan      |
| <input type="checkbox"/> Change Drilling Plan                        | <input type="checkbox"/> Repair Well  | <input type="checkbox"/> Beneficial Reuse of E&P Waste |
| <input type="checkbox"/> Gross Interval Change                       | <input type="checkbox"/> Rule 502 variance requested. Must provide detailed info regarding request. |  |
| <input type="checkbox"/> Bradenhead Plan                             | <input type="checkbox"/> Status Update/Change of Remediation Plans for Spills and Releases          |  |
| <input checked="" type="checkbox"/> Other <u>Alternative MIT</u>     |   |  |

#### COMMENTS:

Renegade requests approval of alternative MIT for the Champlin 75 Amoco K#2 as allowed for by Rule 326.b(3) after Director consideration of any equivalent test or combination of tests.  
Renegade believes the Champlin 75 Amoco K#2 demonstrates mechanical integrity due to a 12/5/2019 bradenhead test (Doc #402261727) performed showing no bradenhead pressure and tubing/casing pressure of 325/345 psi coupled with a 10/21/2020 bradenhead test (Doc #402524173) conducted showing no bradenhead pressure and tubing/casing pressure of 350/360 psi. The Champlin 75 Amoco K#2 was completed with surface casing to 1711' and cemented with 960 sacks. If the well lacked integrity old drilling mud would kill the well and casing pressure would not continue to build. Well pressures including the bradenhead will be monitored monthly to ensure integrity.  
This well is SI as a result of the Third Creek Gas Gathering System shutdown on 6/1/2018 and was producing at the time of SI. The Champlin 75 Amoco K#2 was produced utilizing plunger lift equipment.

#### CASING PROGRAM

(No Casing Provided)

#### POTENTIAL FLOW AND CONFINING FORMATIONS

(No Casing Provided)

#### H2S REPORTING

**Data Fields in this section are intended to document Sample and Location Data associated with the collection of a Gas Sample that is submitted for Laboratory Analysis.**

**Gas Analysis Report must be attached.**

H2S Concentration: \_\_\_\_\_ in ppm (parts per million) Date of Measurement or Sample Collection \_\_\_\_\_

Description of Sample Point:

Absolute Open Flow Potential \_\_\_\_\_ in CFPD (cubic feet per day)

Description of Release Potential and Duration (If flow is not open to the atmosphere, identify the duration in which the container or pipeline would likely be opened for servicing operations.):

--

Distance to nearest occupied residence, school, church, park, school bus stop, place of business, or other areas where the public could reasonably be expected to frequent: \_\_\_\_\_

Distance to nearest Federal, State, County, or municipal road or highway owned and principally maintained for public use: \_\_\_\_\_

COMMENTS:

--

### Best Management Practices

**No BMP/COA Type**

**Description**

--	--

Operator Comments:

This Form 4 is being filed for the Champlin 75 Amoco K#2 in response to a need for an alternative MIT approval to satisfy a COGCC Warning Letter (Doc # 402491859) dated 9/17/2020. Renegade's response to the warning letter has been attached. Conversations with Diana Burn of the COGCC coupled with the well's circumstances has led to the belief that this filing is ripe for approval.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Edward Ingve  
Title: Manager/Owner Email: ed@renegadeoilandgas.com Date: 1/14/2021

Based on the information provided herein, this Sundry Notice (Form 4) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric Date: 2/5/2021

### CONDITIONS OF APPROVAL, IF ANY:

**COA Type**

**Description**

--	--

Data retrieval failed for the subreport 'subreport4' located at: \\DNP\WP004\oFormReports\General\_Cmt.rdlc. Please check th

### Attachment List

**Att Doc Num**

**Name**

402570940	SUNDRY NOTICE APPROVED-OTHER
402572359	CORRESPONDENCE
402592375	FORM 4 SUBMITTED

Total Attach: 3 Files