

Inspection Photos
Location Name: Federal 5-27X
Location ID: 324684



Photo 1. Overview of location taken facing east.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Federal 5-27X
Location ID: 324684



Photo 2. No bradenhead access apparent.



Photo 3. Stained soil at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources