

Inspection Photos

Location Name: FURROW USX AB /15-03P

Location #: 416212



Photo #1

Furrow USX AB 15-03P (05-123-31312)

Abandoned Location | AL

~ 50 yds.

No disturbance or evidence of oil & gas activity