

Inspection Photos
Location Name: Waves 1H
Location ID: 430663



Photo 3 – Wellhead – Stained Soil

Photo 4 – Wellhead – Stained Soil

Inspection Photos
Location Name: Waves 1H
Location ID: 430663



Colorado Oil and Gas Conservation Commission
40.5541, -104.06868, 4837.8ft, 269
02/03/2021 12:50:56



Colorado Oil and Gas Conservation Commission
40.55409, -104.06868, 4837.5ft, 269
02/03/2021 12:51:02

Photo 5 – Gas Engine – Stained Soil – Unused Belts

Photo 6 – Gas Engine – Stained Soil – Unused Belts

Inspection Photos
Location Name: Waves 1H
Location ID: 430663



Photo 7 – Gas Engine – Stained Soil

Photo 8 – Unused Belts

Inspection Photos
Location Name: Waves 1H
Location ID: 430663




Photo 9 – Oily Waste and No Wildlife Covering

Photo 10 – Wellhead – Stained Soil

Inspection Photos
Location Name: Waves 1H
Location ID: 430663



Photo 11 – Oily Waste and no Wildlife Covering at Flare

Photo 12 – Flare – Stained Soil

Inspection Photos
Location Name: Waves 1H
Location ID: 430663



Photo 13 – Heater Treater Shed – Stained Soil

Photo 14 – Heater Treater and Gas Meter

Inspection Photos
Location Name: Waves 1H
Location ID: 430663



Photo 15 – Tank Battery