



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Ant Hill Unit 28-44

API: 05-103-10221

Inspection: 700405278




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Location.

Ant Hill Unit 28-44

API: 05-103-10221

Inspection: 700405278



40.10754, -108.16437, 5875.9ft, 6°
02/02/2021 12:11:03 PM



40.10769, -108.16429, 5892.9ft, 357°
02/02/2021 12:04:59 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Building.

Ant Hill Unit 28-44

API: 05-103-10221

Inspection: 700405278



40.10774, -108.16441, 5895.1ft, 341°
02/02/2021 12:05:25 PM