

Inspection Photos

API: 043-06231

Operator: AUSCO PETROLEUM INC

Inspection Date: 2/9/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06231 | Date: 2/9/2021

Inspection Photos



Photo 1. Facing south along the access road. There is erosion occurring down the road which needs to be repaired and stormwater needs to be diverted off the road. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 2/9/2021

Inspection Photos



Photo 2. Facing southwest toward the location. There is undesirable weeds throughout the location. Interim reclamation has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 2/9/2021

Inspection Photos



Photo 3. Facing southeast at the location. Unused areas of the location have not been reclaimed. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 2/9/2021

Inspection Photos



Photo 4. The topsoil pile are not maintained and have undesirable weeds . The soil piles need to be replaced for interim reclamation. Previous corrective action has not been performed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06231 | Date: 2/9/2021

Inspection Photos



Photo 5. Facing north along the fill slope of the location. There is undesirable weeds (Russian thistle) throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 2/9/2021

Inspection Photos



Photo 6. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 2/9/2021

Inspection Photos



Photo 7. Facing southwest toward the production equipment. Undesirable weed debris needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 2/9/2021

Inspection Photos



Photo 8. Facing toward the sediment trap. Undesirable weed debris needs to be removed out of sediment trap.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 2/9/2021